

## **DMA RO Circular no. 29**

### **EGCS malfunctions**

#### **Interim indication of ongoing compliance in the case of the failure of a single monitoring instrument**

In case of any malfunction that lasts more than one-hour, the Ship Owners or operator shall notify the ship's RO (cc DMA [cfs@dma.dk](mailto:cfs@dma.dk) ) and port state authorities as soon as possible along with an explanation of the steps the Ship Owner or operator is taking to address the failure.

The RO is authorized to act on behalf of The DMA, with ref. to MEPC.1/Circ. 883 Guidance on indication of ongoing compliance in the case of the failure of a single monitoring instrument, and recommended actions to take if the EGCS fails to meet the provisions of the 2015 EGCS guidelines (Res. MEPC.259(68)). Recommend action shall meet the section 9-11 in the mentioned guidance.

The RO must without undue delay notify The DMA [cfs@dma.dk](mailto:cfs@dma.dk) (cc DEPA [mst@mst.dk](mailto:mst@mst.dk) ) regarding temporary remedies and mitigating actions taken and where/when full rectification can be completed in accordance with Danish RO agreement section 15

#### **In case of emission exceedances**

In case an EGCS is not in compliance leading to any emission exceedance or wash water not meeting the criteria, the Ship Owner or operator must inform the Danish Environmental Protection Agency (DEPA) of the incident at [mst@mst.dk](mailto:mst@mst.dk) (cc DMA [cfs@dma.dk](mailto:cfs@dma.dk)) as soon as possible

#### **Relevant legislation and guidance**

- MARPOL Annex VI
- MEPC.1/Circ.883
- Directive (EU) 2016/802